

Repair the "Throw Away" driveshaft that Ford supplied for the F150 Pickup. Yes!! We have a kit for that!!!



 
 R994067
 2004-2008 FORD F150 REAR SHAFT (WELD TO WELD COMPRESSED) - 15 1/2"

 R994067L
 2009-2010 FORD F150 REAR SHAFT (WELD TO WELD COMPRESSED) - 16 1/2"

Call Today For Pricing



The OEM Ford rear driveshafts have a non-replaceable center support bearing. With the Rockford Kit you are able to cut the Original assemblies apart at the friction weld and replace the Slip Yoke, Splined Stub and Center Support Bearing..

1500 11TH AVENUE ROCKFORD, ILLINOIS 61104 PHONE (815) 962-1411 FAX (815) 965-4857