

Year/ Model	Make	OEM Shaft Design	Location	New Drive Shaft No.
MAZDA				
PICKUP (4WD)				
1999-98	B-2500 (Front Drive Shaft)	S9	1	8306C
	B-3000 (Front Drive Shaft)	S9	1	8306C
	B-4000 (Front Drive Shaft)	S9	1	8306C
1997-94	B-2300 & B-3000 W/AT (Front Drive Shaft)	S8	1	8316C
	B-3000 & B-4000 W/MT (Front Drive Shaft)	S8	1	8315C

PROPELLER SHAFTS

Conversion shafts use u-joints & have been engineered to replace the original (OEM) design

