


Year/ Model	Make	OEM Shaft Design	Location	New Drive Shaft No.
<b>MERCURY</b>				
<b>MOUNTAINEER</b>				
1999-97	4WD 4.0L (Front Drive Shaft) . . . . .	S9	1	8306C
	AWD 5.0L (Front Drive Shaft) . . . . .	S9	1	8305C

**PROPELLER SHAFTS**

Conversion shafts use u-joints & have been engineered to replace the original (OEM) design



**Shaft Location**