
Another Option Available from ROCKFORD

Rockford, best known for offering replacement u-joints for the staked-in Honda CRV is now going to offer brand new CRV complete assemblies!!!



If you've ever been frustrated trying to replace the staked-in u-joints on a CRV to find out that the OEM u-joint has been run too long and dug into the weld yoke or flange yoke, we have a solution for you! Rockford now has a new replacement driveshaft... at a fraction of the cost of an OEM replacement!

9201C 1997-2001 HONDA CRV

(OEM - 40100-S10-A01 / 40100-S10-003)

9202C 2002-2006 HONDA CRV

(OEM - 40100-S9A-J01 / 40100-SCA-A01 /

40100-S9A-E01)

9203C 2007-2011 HONDA CRV

(OEM - 40100-SWA-A01 / 40100-SXS-A01)