Year/		OEM Shaft		New Drive
Model	Make	Design	Location	Shaft No.
	OLDSMOBILE			
BRAVA				
2003-02	(Front Drive Shaft)		1	8430C
2001-98	(Front Drive Shaft)	S5	1	8424C
1997-94	(Front Drive Shaft)	S10	1	8406C
1994-91	(Front Drive Shaft)	S1	1	8400C

Conversion shafts use u-joints & have been engineered to replace the original (OEM) design

