

ROCKFORD

Drive Line

TOYOTA TYPE C.V. COMPONENTS

| | PAGE |
|----------------------------|--------------|
| | 25-29 |
| C.V. Centering Repair Kits | 28 |
| C.V. H Yoke | 27 |
| C.V. Head Assembly | 26 |
| C.V. Stud Flanges | 26 |
| C.V. Weld Yokes | 27 |
| Flange Yokes | 27 |
| Misc. Repair Components | 28-29 |
| Universal Joint Sets | 27-28 |

MANUFACTURER OF DRIVELINE COMPONENTS
1500 11TH AVENUE ROCKFORD, ILLINOIS 61104
PHONE (815) 962-1411 FAX (815) 962-4857

| | |
|---|---|
|  | <p>421 -<u>C.V. HEAD ASSEMBLY</u> (Includes 419-2 Ring To Adjust Pilot From 1.875" to 2.437") 4x4 Toyota Thru 1987</p> |
|  | <p>415 -<u>C.V. STUD FLANGE - (1st Design)</u> (Has .470 Dia Stud, 3.575 Bolt Circle & .328 Holes) - (Use With 407-0 Kit) 1979-1984 Toyota 4X4</p> |
|  | <p>415A -<u>C.V. STUD FLANGE - (2nd Design)</u> (Has .511 Dia Stud, 3.575 Bolt Circle & .328 Holes) - (Use With 409-0 Kit) 1985-1994 Toyota 4X4</p> |
|  | <p>415B -<u>C.V. STUD FLANGE - (1st Design)</u> (Has .470 Dia Stud, 3.670 Bolt Circle & .394 Holes) - (Use With 407-0 Kit) 1979-1984 Toyota 4X4</p> |
|  | <p>415C -<u>C.V. STUD FLANGE - (2nd Design)</u> (Has .511 Dia Stud, 3.670 Bolt Circle & .394 Holes) - (Use With 409-0 Kit) 1985-1994 Toyota 4X4</p> |
|  | <p>415D -<u>C.V. STUD FLANGE - (1st Design)</u> (Has .470 Dia Stud, 3.575 Bolt Circle & .394 Holes) - (Use With 407-0 Kit) 1979-1984 Toyota 4X4</p> |

ROCKFORD Drive Line

Supplier of Drive Line
Service Items

| | |
|---|---|
| <p>419 -<u>WELD YOKE - (1st Design)</u> (Uses 1.420 Diameter Seal - Rockford #407-4) - (Includes 419-2 Ring To Adjust Pilot From 1.875" to 2.437") 1979-1984 Toyota 4X4</p> |  |
| <p>420 -<u>WELD YOKE - (2nd Design)</u> (Uses 1.520 Diameter Seal - Rockford #409-4) - (Includes 419-2 Ring To Adjust Pilot From 1.875" to 2.437") 1985-1994 Toyota 4X4</p> |  |
| <p>422 -<u>BOLT FLANGE YOKE - (1st Design)</u> (Height to Bearing Center - 1.430") 1979-1994 Toyota 4X4</p> |  |
| <p>422A -<u>BOLT FLANGE YOKE - (2nd Design)</u> (Height to Bearing Center - 1.765") 1979-1994 Toyota 4X4</p> |  |
| <p>486 -<u>H YOKE - (1st Design)</u> (Center to Center Distance 2.825") 1979-1986 Toyota 4X4</p> |  |
| <p>491 -<u>H YOKE - (2nd Design)</u> (Center to Center Distance 3.075") 1986-up Toyota 4X4</p> |  |
| <p>407-10 -<u>UNIVERSAL JOINT</u> (Fits the C.V. End of the Front Shaft) - (Used With H Yoke, Stud Flange & Weld Yoke) 1979-1994 Toyota 4X4</p> |  CCCC |

Toyota Components

| | |
|---|--|
|  | <p>407-11 -<u>UNIVERSAL JOINT</u> (Fits the Slip End of the Front Shaft, Both Ends of Rear Shaft) - (Used With Bolt Flange) 1979-1994 Toyota 4X4</p> |
|  | <p>407-0 -<u>C.V. CENTERING REPAIR KIT</u> (Fits 415, 415B & 415D Stud Flanges) - (.470 I.D. Ball) 1979-1984 Toyota 4X4</p> |
|  | <p>409-0 -<u>C.V. CENTERING REPAIR KIT</u> (Fits 415A & 415C Stud Flanges) - (.511 I.D. Ball) 1985-1994 Toyota 4X4</p> |
|  | <p>404-2 -<u>SPRING</u> (Included With 407-0 & 409-0 Centering Repair Kits) 1979-1994 Toyota 4X4</p> |
|  | <p>407-4 -<u>TOP SEAL</u> (Included With 407-0 Centering Repair Kits) - (Seal has 1.420 O.D.) 1979-1985 Toyota 4X4</p> |
|  | <p>409-4 -<u>TOP SEAL</u> (Included With 409-0 Centering Repair Kits) - (Seal has 1.520 O.D.) 1985-1994 Toyota 4X4</p> |

ROCKFORD **Drive Line**

**Supplier of Drive Line
Service Items**

407-16 -ADAPTER RING
(Allows 407-4 Seal To Assemble In 1.480 Oversized
Weld Yoke Bore)



Toyota Components

NOTES